

# State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

DQ71

Michael O. Leavitt Governor

Kathleen Clarke Executive Director Lowell P. Braxton Division Director 1594 West North Temple, Suite 1210 PO Box 145801

Salt Lake City, Utah 84114-5801

801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD) INSPECTION REPORT

Partial:	Com	plete:	XXX	Explo	ration:	
Inspection Date & T						
Date of Last						

Permit Number: <u>C/007/034</u> Mine Name: Banning Loadout County: Carbon Permittee and/or Operator's Name: Canyon Fuel Company Business Address: P.O. Box 1029, Wellington, Utah 84542 Prep. Plant XXX Other Type of Mining Activity: Underground Surface Company Official(s): Mr. David Spillman, Senior Mine Engineer, Vicky Miller, consultant State Official(s): Gregg Galecki Federal Official(s): None Weather Conditions: Clear, 50's F / mild breezes Disturbed 21.6 Existing Acreage: Permitted 36 Regraded Seeded Status: Active XXX

# REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - b. For partial inspections check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		<b>EVALUATED</b>	N/A	<b>COMMENTS</b>	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]		[X]	$\Box$
2.	SIGNS AND MARKERS	<u>[X]</u>	Ц	Ц	$\Box$
3.	TOPSOIL	П	[X]	Ц	$\Box$
4.	HYDROLOGIC BALANCE:				
	a. DIVERSIONS	[X]	П	П	П
	b. SEDIMENT PONDS AND IMPOUNDMENTS	<u>[X]</u>	$\Box$	[X]	П
	c. OTHER SEDIMENT CONTROL MEASURES	$\overline{X}$	Π	[X]	П
	d. WATER MONITORING	[X]		[X]	Ш
	e. EFFLUENT LIMITATIONS	<u>[X]</u>	$\Box$	[X]	П
5.	EXPLOSIVES		<u>[X]</u>	[ <u>X]</u> []	П
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	$\Box$	[X]		
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS		[X]	Ц	$\Box$
8.	NONCOAL WASTE	<u>[X]</u>	П	П	П
9.	PROTECTION OF FISH, WILDLIFE AND RELATED				
	ENVIRONMENTAL ISSUES	[X]	$\Box$		$\Box$
10.	SLIDES AND OTHER DAMAGE	П	[X]	П	$\Box$
11.	CONTEMPORANEOUS RECLAMATION	$\overline{\Box}$	[X]	П	Ц
12.	BACKFILLING AND GRADING	$\overline{\Box}$	[X]		
13.	REVEGETATION	<u>[X]</u>	П		П
14.	SUBSIDENCE CONTROL	Ξ	[X]	Ц	П
15.	CESSATION OF OPERATIONS	[X]	$\Box$		П
16.	ROADS:				
	a. CONSTRUCTION/MAINTENANCE/SURFACING	[X]	П	Ц	$\Box$
	b. DRAINAGE CONTROLS	[X]	$\Box$	$\Box$	П
17.	OTHER TRANSPORTATION FACILITIES	[X]	$\Box$		$\Box$
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[X]	$\Box$		$\Box$
19.	AVS CHECK (4th Quarter- April, May, June)	[X]	$\Box$		
	AIR QUALITY PERMIT	[X]	$\Box$	$\Box$	
21.	BONDING & INSURANCE	[X]	[]	[X]	П

### INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: <u>C/007/034</u>

DATE OF INSPECTION: 11/20/2001

( COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE )

**Note:** The Banning site remains in temporary cessation; there is no activity at the site.

# 1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The current UPDES permit for the Banning Siding remains in affect until April 30, 2003.

The Division completed the midterm permit review for Banning Siding on June 1, 2001 with no issues pending.

Amendment AM01D allowed for the storage of Sediment Pond material from the Dugout Mine to be placed at the site. The amendment was approved, executed, and As-builts have been submitted and are pending approval.

### 4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The third quarter impoundment inspection for the site's sediment pond was conducted on September 7, 2001, with no signs of instability or other hazards being reported. Mr. Dave Spillman conducted that inspection. The fourth quarter inspection was conducted concurrent with this inspection. A training session was conducted by Mr. Dave Spillman for Ms. Vicky Miller so she will be sufficiently trained to conduct future pond inspections. This pond is incised.

# 4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

Due to the addition of sediment pond material to the site, a series of berms was placed around both sediment pond material stockpiles. All material was contained within the first berm for both stockpiles. No sediment transport was noted.

### 4D. HYDROLOGIC BALANCE: WATER MONITORING

The third quarter water monitoring report for the Banning Siding Loadout was received by the UDNR/OGM/SLO on November 19, 2001. No water monitoring was conducted during the quarter. The one water monitoring site (Truck dump sump), is required to be sampled annually in late fall. The sample had not been collected as of the day of this inspection.

# 4E. HYDROLOGIC BALANCE: EFFLUENT LIMITATIONS

Discharge monitoring reports for the months of July, August, and September of 2001 were reviewed. There were no outfalls from the sediment pond during this period. All reports were submitted in a timely fashion.

As noted during today's field inspection, the sediment pond was dry. No problems were noted.

# INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: C/007/034

DATE OF INSPECTION: 11/20/2001

## 13. REVEGETATION

Sediment from the Dugout sedimentation pond has been roughened but not seeded. Seed is on order.

# 21. BONDING AND INSURANCE

The current general liability insurance coverage for the Banning site will expire on July 31, 2002.

Inspector's Signature: Stead Haller #48

Date: November 21, 2001

Note:

This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas &

Mining.

cc:

James Fulton, OSM Rick Olsen, Canyon Fuel

Price Field office

 $O: \label{lem:compliance} O: \label{lem:co$